

F-4D 65-0771 390 TFS, 366 TFW, USAF, Da Nang
1Lt V Parkhurst (survived)
1Lt M De Long (survived)

During a flak suppression mission a Phantom suffered an accidental utility hydraulic failure that led to loss of control. Both the crew ejected safely before the aircraft crashed.