

DECLASSIFIED

~~SECRET~~

MISSION NARRATIVE

103

Mission No. 2-3-84

28 Oct 67

At approximately 0715L Hatchet flight made a call on guard that Hatchet 2 had a flameout and was attempting an air restart. A few seconds later Hatchet 2 ejected and Crown 1 proceeded toward the scene. The downed position was 165°/35NM from Ch. 86. A Pedro was scrambled from Udorn RTAFB to make the pickup. Hatchet 3 remaining over the scene established voice contact with the survivor, who was hanging in the trees. Crown 1 arrived over the site established visual contact with Hatchet 3 and Pedro 09 and gave vectors to the scene for Pedro. Pedro 09 made the pickup at 0802L and reported the survivor in excellent condition. The survivor was taken to Udorn RTAFB.