

DET 2, 38 ARUSG, HEST, JAN - MAR 1968

Mission 2-38-02, 9 Mar 68. This detachment was tasked with a mission to investigate a report of a downed CH-30 72 miles south of Takhlī RTAFB, Thailand. Pedro 82 was launched and with the aid of GCI was able to locate the downed helicopter. It was determined that the CH-30 had made an emergency landing due to rotor blade damage. The crew was then removed to Don Mueang RTAFB, Thailand. The crew of Pedro 82 consisted of:

RCC	Maj	Hayden C. Moore
CP	LtCol	Edward J. Renth
MT	SSgt	Joseph A. Voltaggio
FE	Sgt	David M. Bickford
RS	SSgt	Thomas J. Micholson

Mission 2-38-03, 11 Mar 68. An F-105 pilot was forced to eject from his aircraft approximately 60 miles northeast of Takhlī RTAFB. The crew of Pedro 57 was launched and were able to locate the pilot with the aid of his wingman and signals from the downed pilot's beeper. A hoist recovery over approximately 100 foot trees was made and the pilot was returned to the 355th USAF Hospital at Takhlī. The crew of Pedro 57 consisted of:

RCC	Capt	William F. Glover Jr.
CP	Capt	Robert N. Garlow
RS	SSgt	Thomas J. Nicholson
RS	Sgt	Richard W. Turner
MT	Sgt	James R. Reid
FE	Sgt	Douglas C. Unruh